JONES & HERRIN

Architecture/Interior Design

June 28, 1994

Bud Bienvenu, Executive Director, Huntsville Depot Museum 320 Church Street Huntsville, AL 35801

Dear Bud:

In reply to your inquiry, we have pulled from the files the 1980 restoration drawings for the Huntsville Depot Museum Auto Building. In 1980-81, the exterior walls of this building were repaired, and some rebuilt, however, the old built-up roof (which was perhaps 15 years old in 1980 and had some leaks) was patched and kept since money was tight.

This roof is now perhaps about 30 years old and is long past due for replacement. Such asphalt and gravel roofs generally last only 12 to 15 years. We now have available "modified bitumen" roofs which promise to be much more trouble-free than the old asphalt and gravel roofs.

The building is presently a shell of 4-walls (which needs a roof) with no electrical, mechanical, plumbing, partition or finish work on the inside. The shell wall exteriors are past due for maintenance. In cold economic terms, the present value of the shell is probably between 5% and 10% of the cost of a completed building. Since a completed (but not furnished) exhibit building such as this could be expected to cost around \$85 to \$90 per square foot, it would probably cost about \$80 per square foot x 5,685 s.f. of enclosed area, plus about \$40 per square foot x 775 s.f. of canopy area, plus about \$40,000 for site work such as walks, drives, signs, landscaping, etc.

\$80 p.s.f. x 5,685 s.f. enclosed = \$455,000 \$40 p.s.f. x 775 s.f. canopy area = 31,000 \$ite work (l.s.) = 40,000 Approximate Total = \$526,000 (i.e. perhaps \$500,000 to \$550,000)

To this must be added:

- Exhibit costs, to include signage, cases, graphics, artifacts (and their restoration) exhibit design costs, etc.
- 2. Architectural costs = 9.8% of restoration costs
- Owner's administrative costs
- Legal costs (contracts regarding acquisitions, displays, construction, etc.)
- Furnishings
- 6. Equipment

Sincerely,

Harrie P Jones FAIA



DEC. 180

ALTO BUILDING HUNTSVILLE DEPOT HUNTSVILLE, AL DECEMBER, 1980 PROJECT # 80.031 (AMERICAN LEGION BLDG.)

EAST & NORTH FACE



DEC. 180

EAST FACE



DEC 180

EAST FACE



DEC. 180

NORTH-EAST CORNER F



EAST FACE



EAST FACE !



SOUTH . EAST CORNER EAST FACE



DEC. 180

SOUTH & EAST FACE



DEC. '80

SOUTH FACE ENTRANCE



DEC. 180

South FACE 1 METAL BLOG - BRICK BUILDING JOINT



DEC. 180

SOUTH FACE 1 METAL BLDG. SHOWING GARBAGE CAN WASH



DEC. '80

SOUTH FACE 4 BRICK BLDG .- FRONT



DEC. 180

SOUTH FACE METAL BLDG.



DEC. 180

SOUTH FACE METAL BLDG.



DEC. 180

SOUTH WEST CORNER SOUTH FACE



SOUTH & WEST FACE

DEC. 180



WEST FACE

DEC. 180



WEST FACE AT DRAINAGE TUNNEL



DEC. 180

WEST FACE



DEC. 180

WEST FACE AT DRAINAGE TUNNEL



DEC. 180

NORTH FACE



DEC. 180

NORTH FACE 1



DEC. 180

NORTH FACE 1 METAL BLDG. - BRICK BLDG. JOINT



DEC. 180



DEC. 180

NORTH FACE AT STORAGE RM. WINDOWS



DEC. 180

NORTH FACE BRICK BLDG.



DEC. 80

NORTH FACE BRICK BUILDING



DEC. 180

NORTH FACE NORTH - EAST CORNER



DEC. 180

BAGGAGE BLDG. T WEST END (PHOTO TAKEN FROM DEPOT)



DEC. 180

NORTH & WEST FACE (PHOTO TAKEN FROM DEPOT)



Brick flue from kitchen @ South well.





HVAC units on roof.






HVAC units on roof.





Pitch on conc. coping.
North Well ->



North east corner.



Ezst wall.



Roof drains & flashing details. North well.



South Well

Metal roof


Roof vents





Looking West





Looking South



Flashing detail @ connection of built-up root of metal root.



Looking South.



DEC. 180

ASSEMBLY Rm. WEST WALL



DEC. 180

ASSEMBLY Rm. SOUTH-WEST CORNER



DEC. 180

ASSEMBLY RM. EAST WALL GLAZING JAMB



ABOVE ASSEMBLY RM. LOOKING NORTH

DEC. '80



ABOVE ASSEMBLY RM. LOOKING EAST

DEC. 180



HALL OFF ASSEMBLY Rm. LOOKING WEST



DEC. 180

ASSEMBLY RM. SOUTH WALL



DEC. 180

ASSEMBLY Rm. EAST WALL



DEC. 180

ASSEMBLY Rm. EAST WALL



ASSEMBLY Rm. NORTH-EAST CORNER

DEC. 180



ASSEMBLY Rm. NORTH WALL

DEC. '80



DEC. 180

ASSEMBLY Rm.
NORTH-WEST CORNER



HALL OFF ASSEMBLY RM.

LOOKING EAST



DEC. 180

STORAGE BETWEEN OFFICE AND HALL - LOOKING WEST



DEC. 180

MEN'S RESTROOM NORTH-EAST CORNER



KITCHEN NORTH AND EAST WALLS

DEC. 180



KITCHEN SOUTH AND WEST WALLS

DEC. 80



DEC. 180

STORAGE Rm.
(OLD LOUNGE)
NORTH-EAST CORNER



DEC. 180

STORAGE RM.
(OLD LOUNGE)
SOUTH-EAST CORNER



DEC. 180

METAL BLOG. - STORAGE LOOKING NORTH

FROM ATOP WOOD FRAMED CEILING LOOKING WEST AT METAL BLDG. WEBT WALL



DEC. 180



METAL BLDG. NORTH - WEST CORNER

DEC. 180



DEC. 180

METAL BLDG. LOOKING SOUTH-WEST MASONRY PARTITIONED ROOM AT PHOTO CENTER



DEC. '80

RECREATION Rm.
FROM ENTRANCE OFF
HALL LOOKING NORTH-WEST



DEC. '80

RECREATION Rm.
LOOKING NORTH-EAST
OUTSIDE CORNER OF
SAFE @ PHOTO CENTER



DEC. '80

RECREATION Rm. LOOKING SOUTH-EAST INTO HALL



DEC. 180

STORAGE Rm. OFF REC. Rm. LOOKING EAST



DEC. 180

STORAGE RM. OFF REC. RM. A LOOKING WEST



STORAGE RM. OFF REC. RM. LOOKING AT STEEL COL. & CEILING



DEC. '80

METAL BLDG. LOOKING SOUTH-EAST AT OUTSIDE OF WOOD FRAMED ROOMS



DEC. '80

METAL BUILDING LOOKING EAST AT REAR OF WOOD FRAMED ROOMS



ATOP WOOD FRAMED CEILING LOOKING EAST ALONG METAL BUILDING SOUTH WALL

DEC. 180

ATOP WOOD FRAMING
LOOKING SOUTH - EAST
AT METAL BLDG. \$
MASONRY BLDG. JUNCTION



DEC. '80



ATOP WOOD FRAMED ROOMS LOOKING EAST AT WEST SIDE OF MASONRY BUDG.





DEC. 180

ATOP WOOD FRAMED RMS. LOOKING NORTH-EAST



ATOP WOOD FRAMED ROOMS LOOKING NORTH - EAST



ATOP WOOD FRAMED ROOMS LOOKING NORTH - EAST




ATOP WOOD FRAMED ROOMS LOOKING NORTH AT METAL BLDG. AND MASONRY WALL JUNCTION.

DEC. '80

DEC. '80

ATOP WOOD FRAMED ROOMS LOOKING NORTH



ATOP WOOD FRAMED ROOMS LOOKING NORTH AT REMAINING PORTION OF CUT-OUT STEEL TRUSS.

NOTE: SIGNS OF EARLIER
BURNING AND NEW
MASONRY ADDED.

30 por Bridge circue