

JONES & HERRIN

Architecture/Interior Design

October 24, 1997

Dr. Paul E. Jones II
Leigh Place
Leighton, Alabama 35646

Re: Jones Residence

Dear Paul:

I finally got a chance to stop by your house. What an improvement! This bears out what I've always maintained; architecture is 90% proportions. The only difference between April, 1996 and October, 1997 is an adjustment to some of the proportions.

Congratulations on your excellent execution of this work. You have a vastly improved house!

Thanks,



Harvie P. Jones, FAIA
HPJ/tm

copy: HJ

attachment



photo Oct '97 AFTER PROPORTIONAL
REFINEMENTS by J.H. Arch
HP Jones
(See "before" photos of April '96)



9/6



owner's
photo
(detail)

Poor
proportions
on cornice,
pediment,
chimneys
etc.
H. J. to
improve


Dr. Paul Jones Res. - Leigh St. - "Greenwood" - Leighton St.
First Fl. is 1820's log hse. Second fl. & ext. = c. 1960-1995
photos April '96 H. J. Jones for ext. trim & chim. proportional improvements



owner's
photo
()

"BEFORE"
(see Oct
'97 "AFTER"
photos)

DR. PAUL JONES
1820-1990
LEIGHTON ST.



LEIGH ST

STORES
MAIN ST

photos taken
in bridge.

North
front



PH

MBH
Roof

N
P



Portico
1st & 2nd fls.,
design by
owner



N
P

PH



Upper blinds
nailed forward,
backward.
Chim, too
skinny

306



W. Wing (was built as gar.,
now a sitting rm.)

WEST
WING
N. FRONT



Porch
preparations





Owner's
photo
↙

→ N

Roof too big
for wing

Chim.
too skinny



→ N



→ N

646



SOUTH
REAR





21

115

Part of this is an early 19th c.
servants' house.
Owner intends to demolish

649