

PS - Mrs. Staff moved & rebuilt
1994 w/o architectural guidance.



N.
F.

PS, 1993 - Disassembled & reassembled
in new site by Burritt staff (C. Painter) -
much better job.



N

BURRITT MUSEUM LOG HSE BUILT IN 1960'S ↗
S.E. POINT OF ROUND-TOP MT., HUNTSVILLE AL,
USING 1840'S LOGS ONLY. REST IS 1960'S CONCRETE, DONE W/O PROFESSIONAL GUIDANCE. PHOTOS NOV. 1990 HAVE IT WRONG PATH



(PHOTOS
MADE FOR
PREP. FOR
REBUILDING
HST TO
BETTER HST,
STD'S.
NOT DONE
AS OF 1991)
PS - executed
1994 by
Burritt staff
S. WALL



DETAILS & MATERIALS NOT LIKE 1840'S. NM BY N JONES.

SACUILLATION
25M-07
5061-0581



Chim. not gen
1840 Details


→ N



H

Dgnt

→ N




3066





Lage is
+ cont'd
twist
over
(awkward)

21



West Pen

H



N



West Room ✓ N

A

5 Oct 6



12



E 257
PCN

12

24





East Room

— H