

10/22
1926 Gerson House
509 Easton Ave, Huntville AL
photos Mar. 1964 H.P. Jones FR 116
for new pergolas (not built)

(1990 owned Dr. Gerry Brooker)

At 1-sty wing roofs,
roof-board trims = original but were plain.
∴ Owner wanted to remove in c. 1988.
Instead HJ added backband moulds, which
made them ok



509 EASTON
BROOKER



NH

Remod wing c. 1988 ADA, J & H Architects, H Jones (except arch = per owner, HJ had 3 sets of windows)



SE



NH



NH

2092



509 Euclid Ave, N'ville Nl. (1926 GERON HST.)
Gerry Brooks, 1992 owner
photo May 1992 NP Jones, FOLK, for real address.



→ N



1993

↙

2003



→ N



↓ N

303

W



W



W

3 bricks + 3 jo = 8 1/2" h.

1 brick + 1 jo = 8 1/2" h.

23 courses x 8 1/2" = 65.14" = 5'-5 1/8"

16 courses x 8 1/2" = 45 1/3" = 3'-9 1/4"



Soldier lintel

8" 80

22

Fd

160





SCT

F1


3/4\"/>

16\"/>



NOTE

Corz
Watertbl.
in photos




K1

Garry Proctor Res



13 May '92

509 Enata Ave 35801

509 Travis Dr 13 May 92 (Brocato)



FL 2
(ceiling 9')



Sill 42
above
landing

FL 1
ceiling 9'

KIT.

Gerry Davento Pro Add

509 t/mtr (Ar 3580)

6 May 92

Den / Study on fl 1
Fl. 2 -

one unit for 2 fl

