

Dark lines = profile of 1920's 2 story porch. Sketch = 1920's, w/ porch

orig. 1850's + ADDN, 1850-1850's MID-1850's



1. East wall has one orig. sash. All these are c. 1920's (4/1)
2. See 1861 map + 1871 view for orig. small portico
3. Partly restored 1878-79 (portico only) Jones + Herin Arch. - H Jones + R. Allen. Fake little sash-blinds are by owner, + barn-roofing on portico.
4. Porch size + roof slope based on traces on wall + uncovered porch Endn. wall. Details similar to Cabaniss Hse, also by Steele.

FIGURES hsc 1840's + 1850's (Pat Ryan)

423 of orig. entry
 FIGURES 1456 423 Randolph Ave
 late 1840's (west) + mid 1850's (east)
 GEORGE STEELE, ARCH.
 photos 1978, R. Nilon + H Jones



sketch of 1920's porch
(± 2' sq. stucco cols.)

See E. wall for
div. of sash (1)



DN DASH LINES = PROFILE OF 1920'S
2 story porch. Stucco = 1920's, w/ porch



DN ORIG. HSE. 1840'S → → ADDN. MID-1850'S

1. EAST WALL HAS ONE ORIG. SASH
ALL THESE ARE C. 1920'S (4/1)
2. SEE 1861 MAP + 1871 VIEW
FOR ORIG. SMALL PORTICO
3. PARTLY RESTORED 1978-79
(porch only) Jones + Hermin
Arch. - H Jones + R. Allen
Fake little sash-blinds are
by owner, + barn-roofing
on portico.
4. Porch size + roof slope based
on traces on wall + uncovered
porch fndn. wall. Details
similar to Cabanis Hse,
also by Steele.

DN

← E of orig. entry
FIGURES HSE 423 Randolph Ave
late 1840's (west) + mid 1850's (east)
Georbt STEELE, ARCH.
photos 1978, R. Allen + H Jones



NW

Uncovered 1850's foundation of 1850's portico

NW




tapered per
1800-1860
practice, may
be orig.

NS



SW Corner



end-cap probably orig.
(is typical)



1980 photo, after renov. by
 Patricia Ryan (still for apts)
 barn roof & skinny stock blinds
 NOT per J&H arch.

N



S.W. Corner

N