

1866 Kaufman bldg  
 1986 photos - H. Jones  
 for facade restor.  
 per 1866 contract  
 & 1867-72 photo  
 (executed)

Eustis  
 Ave



Photo 1 Looking S.E. Kaufman Store in center.

(denol. 1872 Dentler (1950± land)) | 1867-72 Bldg | 1866 Kaufman | 1852 frame



Photo 2 Looking E.S.E Kaufman Store in center.



Photo 3 Looking E.S.E at ground floor. Clerestories are boarded over.



Photo 4 Looking north at near ( 2 and 2/3 story).




Photo 6 Second floor modern finishes. Cell is dropped about 16 inches below original plaster ceiling.



Photo 5 Stair to 2nd floor.



Main floor looking from entry south to rear.

Photo 7



Photo 8 Basement.

Circa 1866 Kaufman Store  
206 Eustis Ave, Huntsville, Alabama 35801  
Photographer-Harvie P. Jones, F.A.I.A.