





There is black ink writing on the back which reads: "T-24"














There is a still caption on the back which reads: "STOWAGE RACKS BEING INSPECTED AFTER PRE-FIT CHECKOUT. OWS NO-1."










There is black ink writing on the back which reads: "T-23"













There is a still caption on the back which reads: "INSPECTING FOOD FREEZER & REFRIGERATION SUBSYSTEM IN UPPER LEVEL OF OWS NO. 1."














There is a still caption on the back which reads: "FAN CLUSTER, FOOD FREEZER AND REFRIGERATION SUBSYSTEM IN UPPER LEVEL OF OWS NO. 11"

























There is a still caption on the back which reads: "CHECKING OUT TO-63 CAMERA ASSEMBLY MOUNTED IN OWS NO-1 SCIENTIFIC AIRLOCK"




There is a still caption on the back which reads: "OPERATING TO-63, 35MM CAMAERA ASSEMBLY DURING CHECKOUT IN SCIENTIFIC AIRLOCK. OWS NO-1."











There is a still caption on the back which reads: "OVERALL VIEW OF UPPER LEVEL EXPERIMENT/STORAGE AREA IN LEFT FORGROUND: ASTRONAUT MANEUVERING UNIT IN CENTER BACKGROUND: OWS FILM VAULT."

